

Renergy Land Application Operator Daily Log

*NOTE: All information required to be completed

Site #: MOs - 01 - 07Date: 1/8/19Hours of Operation: 7 am to 10 am pmWeather Conditions: Overcast

Are signs posted? Yes No Buffers Flagged? Yes No
 Does the field have drainage tiles? Yes No
 Are tile outlets plugged? Yes No
 Inspected for suitable risers, hoses, and connectors at: Start up In process End day/field

Method of application? Surface application InjectionApplication rate per acre: 10-12 K

Number of loads to site: _____

Gallons applied to this site on this date: 21,790Approximate acres applied on this date: 1.8Notes: NO E.T. yet

Operator Name: _____

Operator Signature: _____

Call Taylor Faecher (513) 476-1663, Environmental Compliance Specialist
 Call Logan Randles (614) 961-6713, Director of Operations

Renergy Land Application Operator Daily Log

*NOTE: All information required to be completed

Site #: MOS-01-07Date: 1/10/19Hours of Operation: 7 am to 4 pmWeather Conditions: Sunny 26°

| | | | | | |
|--|------------|----------|------------------|---------------|----|
| Are signs posted? | <u>Yes</u> | No | Buffers Flagged? | <u>Yes</u> | No |
| Does the field have drainage tiles? | <u>Yes</u> | No | | | |
| Are tile outlets plugged? | <u>Yes</u> | No | | | |
| Inspected for suitable risers, hoses, and connectors at: | | Start up | In process | End day/field | |

Method of application? Surface application InjectionApplication rate per acre: 10-12 tNumber of loads to site: 0Gallons applied to this site on this date: 4561,680Approximate acres applied on this date: 27.5

Notes: _____

Operator Name: RAW HANDLING LLCOperator Signature: [Signature]

Call Taylor Faecher (513) 476-1663, Environmental Compliance Specialist
Call Logan Randles (614) 961-6713, Director of Operations

Renergy Land Application Operator Daily Log

*NOTE: All information required to be completed

Site #: PMOS-01-07Date: 11/9/19Hours of Operation: 6:30 am/pm to 5 am/pmWeather Conditions: Over cast 34

| | | | | | |
|--|------------|-----------------|-------------------|----------------------|----|
| Are signs posted? | <u>Yes</u> | No | Buffers Flagged? | <u>Yes</u> | No |
| Does the field have drainage tiles? | <u>Yes</u> | No | | | |
| Are tile outlets plugged? | <u>Yes</u> | No | | | |
| Inspected for suitable risers, hoses, and connectors at: | | <u>Start up</u> | <u>In process</u> | <u>End day/field</u> | |

Method of application? Surface application InjectionApplication rate per acre: 10-12Number of loads to site: 0Gallons applied to this site on this date: 495,310Approximate acres applied on this date: 51.4

Notes: _____

Operator Name: TALOR HANDLING LLCOperator Signature: [Signature]

Call Taylor Faecher (513) 476-1663, Environmental Compliance Specialist
Call Logan Randles (614) 961-6713, Director of Operations